



CHANGE NOTICE

Effective Date: JANUARY 1, 2013
Log Number: CN-01-443
Subject: EST CONVEYOR "DUAL CLUTCH SPRING" ROCKER ARM ASSEMBLY
PN 13508.44 R-L, 13508.45 L-R
Model Affected: EST-44/EST-66

EST CONVEYOR "DUAL CLUTCH SPRING" ROCKER ARM ASSEMBLY

CMA has added a second "Clutch Spring" to the conveyor rocker arm. This standardizes the EST-44 and -66 Conveyors, and equips the conveyor system with additional torque for pushing heavier racks through the machine; also, this added "Clutch Spring" will help push the racks around tables with 90-degree turns.



12700 KNOTT STREET
GARDEN GROVE, CALIF. 92841
800-854-6417 • 714-898-8781
FAX 714-895-2141
www.cmadishmachines.com