




# CHANGE NOTICE

**Effective Date:** OCTOBER, 2009  
**Log Number:** CN-09-415  
**Part Description:** CAM TIMER  
**Model Affected:** ALL LOW TEMP MACHINES



## **SANITIZER CAM**

The Sanitizer Cam has been secured (glued) in position to prevent the sanitizer from being injected too early into rinse cycle. The 3-4 second delay will assure water has entered the tank preventing sanitizer from coming in direct contact with wash tank.



12700 KNOTT STREET  
 GARDEN GROVE, CALIF. 92841  
 800-854-6417 • 714-898-8781  
 FAX 714-895-2141  
[www.cmadishmachines.com](http://www.cmadishmachines.com)