





CMA PRODUCT IMPROVEMENT

Effective Date: MAY 2015
Log Number: CMA-PI-462
Subject: EST-44/66 WASH MANIFOLD
Models Affected: EST-44, EST-66

EST-44/66 WASH MANIFOLD

The newly engineered “Wash Manifold” improves the flow rate to the upper and lower wash arms. The Stainless Steel pump discharge line centered on the Dual Wash Manifold provides a better balanced flow rate to the Wash Arms, which inturn provides a more consistant spray pattern over the dishes.



12700 KNOTT STREET
GARDEN GROVE, CALIF. 92841
800-854-6417 • 714-898-8781
FAX 714-895-2141
www.cmadishmachines.com